

OFFICIAL INSPECTION REPORT

Continuation Sheet

GLENN COUNTY ENVIRONMENTAL HEALTH DEPARTMENT

257 North Villa Avenue, Willows, CA 95988
Phone (530) 934-6102 FAX (530) 934-6103

Page 2 of 2

Name of Facility/ DBA: <u>The Maple Garden</u>	Inspection Date: <u>11/13/15</u>
Address: <u>724 Fourth St, Orland</u>	
Owner/Permitee: <u>Wei Quan Mai</u>	

Comments:

Other Violations (Continued)

- 41) Repair/replace leaking backflow prevention device on dishwasher machine.
- 41) Provide backflow prevention device at spray hose connection at south kitchen wall by prep sink.
- 41) Repair leak at right faucet assembly of 3-compartment sink. It leaks when turned on.

Received By:

112492

REHS:

John H. Wells